



Anhydrous Hydrogen Chloride

Hydrogen Chloride is a high pressure liquefied gas, toxic and corrosive acid

HCl, Halogen Acid

CAS# 7647-01-0

UN# 1050

Molecular Weight 36.46

Liquefied Gas with Vapor Pressure of 613 psig @ 70°F (21°C)

Gas Density of 0.095 lb/ft³, (1.522 gm/l) @ 70°F (21°C)

Liquid Density of 52.7 lb/ft³, (0.842 kg/l) @ 70°F (21°C)

Toxic Gas with TLV and PEL of 5 ppm, LC₅₀ 3120 ppm, IDLH 50 ppm

Shipping Labels Poison Gas and Corrosive

Boiling Point, 1 atm. -121°F (-85°C)

Freezing Point, 1 atm. -173.6°F (-114.2°C)

Critical Temperature 124.5°F (51.4°C)

Hydrogen Chloride has a vapor density heavier than air. - 1.266

Gas Specific Volume @ 70°F (21°C) - 10.55 ft³/lb (657 cc/gm)

Autoignition - Not Flammable

Flammability (LFL -UFL) - Not Flammable

Thermal Stability - Hydrogen Chloride is thermally stable

Water Solubility - Hydrogen Chloride is very soluble in water

Odor - Hydrogen Chloride is reported to have a sharp irritating odor

Latent Heat of Vaporization -121°F (-85°C) - 205.5 btu/lb (478 kJ/kg) at Boiling Point

Hydrogen chloride is used in many applications. It has a high vapor pressure and is extremely soluble in water. It is extremely corrosive when hydrolyzed with the moisture in the air to form hydrochloric acid.

Chemically Speaking LLC



Fig. 1: HCl Cylinder Leak

Most Electronic grade HCl in the US was shipped in a insulated refrigerated railcar by Dow Chemical to the gas supplier for repackaging. These railcars are designed to ICC-105A-600W specification with a design pressure of 600 psig, they had a pressure rating 425-450 psig which less than the HCl vapor pressure at 70°F of 630 psig.^{1,2} They filled with cold HCl (-50°F) a saturated vapor pressure of 76 psig. While it has been estimated that it would take 30 days for it to warm to a temperature of 47°F activating the 450 psig pressure relief device, the Dept of Transportation requires these to reach their destination within 10 days to insure that they do not.²

The older railcars (89,000 lbs) had a refrigeration coil in the railcar to cool the liquid HCl to -20°F.



Fig. 2: Older HCl Railcar with Cooling Coil



The larger railcars (150,000 lbs) did not have a cooling coil, instead a heat exchanger is mounted on top of the railcar at the gas supplier site to condense and cool the HCl vapor. The liquid returning back to the railcar to keep the liquid cold.

During Katrina (2005) this was not possible at a gas supplier filling facility in New Orleans, LA. Due to flooding electric power was lost for many weeks. This allowed the vapor pressure to build to unsafe levels over many days. The typical pressure relief device has a metal rupture disk that blew at 450 psig into a spring loaded relief valve which reset at 275 psig.



Fig. 3: HCl Railcars In Flood

Periodically workers would row out to the railcars and vent some HCl gas directly into the flood waters to cool the HCl in order to drop the pressure to prevent the pressure relief device from activating and venting the gas into the atmosphere.

Dow Chemical due to safety concerns of transporting the railcars throughout the US announced in 2006 that they would no longer ship railcars. Since they were the only qualified source for most pharmaceutical and semiconductor companies they continued until 2012. Air Products and Linde formed the Anhydrous Hydrogen Chloride a 50-50 Joint Venture Hydrochlor in 2011.

Hydrochlor built a facility immediately outside of Dow's Freeport, Texas, site to process and repackage HCl into a tube trailer with HCl supplied via pipeline. The facility, was commissioned in the second quarter of 2012.

Hydrochlor sold HCl exclusively to the joint venture partners, who continued to market HCl independently. In 2021 it was announced by Dow Chemical (Now DuPont) that the process would be shutdown by Jan 1, 2022.



Niacet a supplier in Niagara Falls, NY has HCl byproduct, they purchased the assets of Alexander Chemical and are supplying the industry since Jan 1, 2022. They are on a steep learning curve regarding purity, cylinder conditioning, analysis, stuck/corroded valves, etc.

HCl is supplied in cylinders, ton cylinders and tube trailers.



Fig. 4: HCl “Ton” Y Container

Incidents

Because of its high vapor pressure and corrosivity, HCl has been involved in numerous incidents. The following are significant incidents.

Pressure Relief Device (PRD)

Because of the high vapor pressure, HCl cylinders have a combination pressure relief device, (CG-4) which is a 165°F fuse metal with a metal rupture disk sized for the cylinder pressure rating. In some rare cases the rupture disk might not have sealed properly or is defective exposing the fuse metal to the pressure of HCl. With this high vapor pressure the fuse metal will cold flow until it starts to leak.



Fig. 5: Fuse Metal That Extruded Until the HCl Leaked




Figs. 6 and 7 : Leaking HCl PRD Fully Activates

Chemically Speaking LLC

Residence, June 5, 1996

In one incident a HCl Cylinder for unknown reasons was partially buried in a residential yard for years. It started to leak at some point corroding the cylinder and valve over time. It was not until the leak got worse that the homeowner called 911.



Figs 8, 9 and 10: Buried Cylinder Solebury Township, PA

Cylinder Rupture 1969, US

At a gas supplier facility where HCl was filled into trailers and cylinders from a refrigerated railcar. The practice, at the time, was to top off returned HCl cylinders. The operator would put the cylinder on the scale, take its weight, subtract its tare weight, then add enough HCl to end up with 65lbs net. One day after filling several cylinders, one of the cylinders began to heat up. Upon noticing it, the operator called to his supervisor and they decided to move the cylinder outside and away from the building. Before they got the cylinder outside of the building it ruptured violently, killing both men.

The investigation revealed that the cylinder had gotten backfilled with nearly 20 lbs of propylene, at a customer's site. The difference in densities between propylene and HCl meant that the cylinder was nearly hydrostatically full. The exothermic addition reaction that ensued heated the cylinder and raised the internal pressure to the bursting pressure of the cylinder.

Topping off cylinders was banned throughout the company as a result.

Tube trailer flex line shear, 1985? US

Gas supplier filling HCl cylinders from tube trailer. A shutoff valve failed and the operator was instructed to not startup the system. He proceeded anyway. After he opened the trailer valve the 6,000 psig rated braided stainless steel hose sheared. The plant manager donned an SCBA and attempted to close the system valve by climbing on top of the tubes. He could not reach the valve. He finally climbed down and grabbed the hose and closed the valve.



It is not known if corrosion was the cause of the failure or if the line was overpressurized at some point when liquid HCl was trapped in the line. As a Best Practice many companies will have a time limit on how long a flexible hose can be used.

Tube Trailer Rupture, 1990, US

A returned tube trailer was refilled with HCl. The practice was to weigh the tube trailer to determine the amount of residue. This was assumed to be distributed evenly throughout the 8 tubes. It was then filled with cold HCl from a refrigerated railcar. As the HCl warmed up it expanded and the liquid filled a tube causing it to rupture the next morning. No injuries



Fig. 11: Ruptured Tube Flew Over 800 ft



Fig. 12: Tube Trailer With the Adjacent Tube Dislodged

Investigation determined that a tube was contaminated with cotton oil (1650 lbs) at the user site. It was filled with 2,600 lbs of HCl until it stopped flowing. It ruptured at an estimated pressure of 7000 psig, (due to the BLEVE) rapidly expanding liquefied gas tearing the tube into pieces. The tube was torn into two major pieces. The largest section consisting of ~80% of the tube ripped through the bulk head of ½" steel and landed 837 feet away. Trailers are now no longer filled with any residue. They must all be emptied before fill

User Site, Tube Cracked, 1990, US



Three tube trailer at user, site cotton delinting suddenly developed a crack 18” exterior and 4 ft interior, releasing the HCl. No injuries and minor damage. Moisture causing interior corrosion appeared to be the root cause.. There were not further incidents like this

Transportation, Tube Trailer PRD Leak, May 12, 2014, US

Leaking PRD noted by a driver on Route 85. ER team packed tube with dry ice to cool
Decision to cold coil transfer into an “empty” trailer. Empty trailer from Texas drove 20 hours to act as a reservoir for cascading the HCl. Dry ice on the tube surface was used to enhance the transfer.



Fig. 13: Leaking Tube Trailer

Emergency Response

To isolate a small leak the following device was designed, tested and patented for HCl tube trailers. It provides the ER team with a system to quickly isolate a leak and convey it to a scrubber where it can be neutralized while it is being transported to another location or plans are prepared to transfer it in place into another trailer

Chemically Speaking LLC



(12) **United States Patent** (10) Patent No.: **US 7,448,402 B2**
Martrich et al. (45) Date of Patent: **Nov. 11, 2008**

(54) **LEAK CONTAINMENT APPARATUS FOR REACTIVE GASES** 4,489,679 A * 12/1984 Holt 122/451 S
 5,086,804 A 2/1992 Ngai
 5,158,204 A * 10/1992 Martrich et al. 220/727
 5,482,536 A 1/1996 Ngai et al.
 5,588,461 A * 12/1996 Pecnik 137/312
 5,636,666 A * 6/1997 Matern 141/51
 6,003,540 A * 12/1999 Benni et al. 137/312
 6,139,806 A * 10/2000 Nickens et al. 422/168

(*) Notice: Subject to any disclaimer, the term of this patent is extended or adjusted under 35 U.S.C. 154(b) by 23 days. * cited by examiner
 Primary Examiner—Kevin L. Lee
 (74) Attorney, Agent, or Firm—Lina Yang

(21) Appl. No.: **11/590,029**
 (22) Filed: **Oct. 31, 2006** (57) **ABSTRACT**

(65) **Prior Publication Data**
 US 2008/0099075 A1 May 1, 2008

(51) **Int. Cl.**
F16K 35/00 (2006.01)
F16J 13/02 (2006.01)
F17C 13/06 (2006.03)


(52) **U.S. Cl.** 137/15.11; 137/312; 137/382; 220/724; 73/49.2; 73/49.3

(58) **Field of Classification Search** 137/312, 137/377, 382, 15.11; 220/724, 725, 728, 220/323, 324, 326; 73/49.2, 49.3, 46
 See application file for complete search history.


(56) **References Cited**
 U.S. PATENT DOCUMENTS
 4,241,846 A * 12/1980 Murphy 220/318

22 Claims, 7 Drawing Sheets


Fluid storage and leak containment comprising (a) a fluid storage vessel comprising at least one vessel having an interior, an exterior, and an outlet opening between the interior and the exterior; (b) a fluid flow fitting sealably connected to the outlet opening and adjacent the exterior of the at least one vessel, wherein the fluid flow fitting is adapted for withdrawing reactive gas from the interior of the vessel; and (c) a containment enclosure having an interior, an exterior, an open end, and an extraction port adapted for the withdrawal of gas from the interior of the containment enclosure, wherein the open end is adapted to fit over and around the fluid flow fitting such that the containment enclosure surrounds the fluid flow fitting and is adapted to collect any reactive gas leaking from the fluid flow fitting.



Setup for small leak <50 cc/min



Setup for large leak >50 cc/min



Sigri ERCV Flange Seizure



The Sigri ERCV breach closure has proven to be sensitive to HCl corrosion of the threads which causes it to seize and gall shut. At least 3 Sigri ERCV's have been cut apart due to HCl leakage. Making it impossible to open even with plates welded to the door for mechanical leverage.



Fig. 5: Plate Welded Onto Door In Attempt to Open ERCV

Repeated attempts to open the door failed so the ERCV, has to be cut open using a torch or a saw.



Eugene Ngai

Eugene Ngai

References

1. Novak, T. and Snyder, M.D., "Playing it Safe With Anhydrous Hydrogen Chloride", Industrial Fire Chief, July/August 1995, pp 27-29



2. C. H. Drury, "Rail transportation of hydrogen chloride anhydrous", The Canadian Journal of Chemical Engineering, Industrial Section, October 196 <https://doi.org/10.1002/cjce.5450390511>
3. Letter to Bill Barlen, Technical Director CGA from Jack B Kelley, Inc, "Safety Alert Item HCl Tube Rupture, Feb 26, 1990
4. US Patent No. 7448402 "Leak Containment Apparatus for Reactive Gases", Nov. 11, 2008

